Le mot de passe administrateur du switch Aruba 3810M n'était pas connu. Nous avons donc procédé à un factory reset de l'équipement. La procédure de réinitialisation a été réalisée en suivant la documentation officielle HPE :



Après le reset, un port du commutateur affichait un voyant orange, indiquant une anomalie.

Pour pouvoir administrer le switch à distance depuis son poste, nous avons activé le SSH. En générant la paire de clés RSA et en activant le service

Ensuite, nous avons physiquement constaté que le module SFP/SFP+ installé n'était pas compatible avec le switch Aruba. En effet, notre module ne correspondait pas aux modules compatibles listés dans la doc HPE :


HPE
Support Center
English
Find in document
Aruba 3810M - Product Information Reference
Table of contents
Overview
Specifications
Compatibility/Supportability
Option Parts
New model specific parts list
Modules
Transceivers
Cables
Power supply
Fan tray
Mounting kit
Software
As a Service
Spare Parts
Software Compatibility
Useful Links
Compatibility/Supportability
Transceivers
Transceivers
Find in table
Description
Option Part Number
Aruba 100 m Small Form-Factor Pluggable Lucent Connector (LC) FX 2 km Multi-Mode Fiber (MMF) transceiver
J9054D
Aruba 1G Small Form-Factor Pluggable RJ45 T 100 m Cat5e transceiver
J8177D
Aruba 1G SFP LC SX 500 m Optical Mode (OM2) MMF transceiver
J4858D
Aruba 1G SFP LC LX 10 km Single-Mode Fiber (SMF) transceiver
J4859D
Aruba 1G SFP LC LH 70 km SMF transceiver
J4860D
Aruba 10G SFP+ LC Short Range (SR) 300 m OM3 MMF transceiver
J9150D
HPE Aruba Networking 10G SFP+ LC LR 10km SMF Transceiver
J9151E
Aruba 10G SFP+ LC Long Reach (LR) 10 km SMF transceiver
J9151D
Aruba 10G SFP+ LC Long Reach Multimode (LRM) 220 m OM2 MMF transceiver
J9152D
HPE Aruba Networking 10G LR SFP+ LC 10 km SMF C-Class transceiver
S2P31A
HPE Aruba Networking 10G ER SFP+ LC 40 km SMF C-Class transceiver
S2P32A
HPE Aruba Networking 10G SR SFP+ LC 400 m OM4 MMF C-Class transceiver
S2P30A
Aruba 10G SFP+ LC Extended Reach (ER) 40 km SMF transceiver
J9153D